

MyHOME_Suite

Version history

Version: 3.4.25	Date: 4th October 2019
F454, F453AV, F453: field "ID Gateway", in MyHome portal chapter, now accept up to 7 characters	
Version: 3.4.18	Date: 21th June 2019
MyHome Screen 10" Capacitive; fixed a bug that occur during configuration of IrSplit in basic mode	
New integrated products programming	
Classe 100 X16E: 344682 (only firmware update)	
Version: 3.4.15	Date: 25th January 2019
Fixed possible crash during creation of "new home"	
Restored link to manual and guide	
New products managed by virtual configuration	
Basic probe with wired sensor: 3454	
Version: 3.4.7	Date: 18th October 2018
Minor bug fix	

Version: 3.4.4	Date: 27th June 2018
<p>F422: added full configuration capabilities</p> <p>MH202: added ability to duplicate a scenario</p>	
New products managed by virtual configuration	
<p>K4652M2, K4652M3, K4672M2L, K4672M2S, KW4691, KG4691, KM4691, K4659</p>	

Version: 3.3.73	Date: 8th May 2017
<p>New icons for Classe300 BT-344612, 344613, 344622 (the firmware must be 2.00.06 or higher)</p>	

Version: 3.3.70	Date: 26th October 2016
<p>Fixed a problem with actuator test function</p> <p>Fixed sporadic crashes</p> <p>Minor bug fix</p>	

Version: 3.3.65	Date: 05th August 2016
<p>Fixed sporadic problems opening old projects:</p> <ul style="list-style-type: none"> • MyHOME_Screen 10 C capacitive MH4892C, MH4893C, 067219, 067228 • Web Server F454 	

Version: 3.3.60	Date: 22th July 2016
<p>MyHOME_Screen 10 C capacitive MH4892C, MH4893C, 067219, 067228: bug fix</p> <p>Several optimizations and minor bug fixing</p>	
New integrated products programming	
<p>Classe 300 X13E: 344642, 344643 (only firmware update)</p>	

Version: 3.2.78	Date: 9th March 2016
<p>MyHome System:</p> <ul style="list-style-type: none"> - Thermostats H4691, LN4691 and 067459 produced after week 16W06: management of the new functions - MyHOME_Screen 10 C capacitive MH4892C, MH4893C, 067219, 067228: bug fix - Web Server F454: fixed sporadic conversion problem between version 1 and 2 <p>Hotel system:</p> <ul style="list-style-type: none"> - MH201 and 003593: management of version 3 - MH201 and 003593: fixed sporadic error during upload - <p>Access control:</p> <ul style="list-style-type: none"> - Central unit 348040: management of version 2.3 - Module GPRS 348330: management of version 1.1 <p>Several optimizations and minor bug fixing Tested with Windows 10</p>	
New integrated products programming	
-	
New products managed by virtual configuration	
-	

Version: 3.1.104	Date: 19th January 2016
-	
New integrated products programming	
-	
New products managed by virtual configuration	
2 relays+N actuator control: LN4672M2, H4672M2, AM5852M2, 067561, 064195, 064196, 064393	

Version: 3.1.94	Date: 26th October 2015
<p>MyHome System:</p> <ul style="list-style-type: none"> - Fixed errors in sensors configuration and related parameters <p>Hotel system:</p> <ul style="list-style-type: none"> - MH201 and 003593 configuration updating: possibility to set fancoil speed in scenario action <p>Optimizations and minor bug fixing</p>	
New integrated products programming	
<p>MyHOME_Screen 3.5 Version 4: LN4890, LN4890A, HW4890, H4890, AM4890, 573958, 078479, 067292 Webserver A/V bus Version 2: F454, 003598 Scenario Manager : MH200N, 003565 (only via Ethernet)</p>	
New products managed by virtual configuration	
<p>Dimmer energy saving lamps bus: F418U2, 003651 1 relay actuator 2 modules DIN bus: 003847 2 relay actuator 2 modules DIN bus: 003848 Dimmer 6 channels: 002627 8 channels DALI/SCS interface: BMDI1100, 002633 Wall mounted sensor long range: 048834</p>	

Version: 3.0.125	Date: 10th July 2015
<p>Bug fixing:</p> <ul style="list-style-type: none"> - possible coexistence problem with TiSferaDesign software - problems of user permissions in some PCs - problem converting some configuration files of MyHomeScreen 10" - function "copy room" in Hotel system 	
New integrated products programming	
-	
New products managed by virtual configuration	
-	

Version: 3.0.118	Date: 22th June 2015
<p>Hotel system: creation of Hotel file able to manage Multi PC function (up to 10 Hotel Supervision Software in the same hotel)</p> <p>Optimizations and minor bug fixing</p>	
<p>New integrated products programming</p>	
<p>MyHOME_Screen 10 resistive: MH4892, MH4893, 067267, 067268 MyHOME_Screen 10 C capacitive (ready for coming launch): MH4892C, MH4893C, 067219, 067228</p>	
<p>New products managed by virtual configuration</p>	
<p>-</p>	

Version: 2.0.111	Date: 20th March 2015
<p>Optimizations and minor bug fixing</p>	
<p>New integrated products programming</p>	
<p>-</p>	
<p>New products managed by virtual configuration</p>	
<p>-</p>	

Version: 2.0.104	Date: 6th February 2015
<p>Fixed possible problem opening some configurations file made with version 1.x</p>	
<p>New integrated products programming</p>	
<p>-</p>	
<p>New products managed by virtual configuration</p>	
<p>-</p>	

Graphics interface:

- Main page with definition of type of project (MyHome or Hotel)
- A single view for virtual and product programming

MyHome system:

- Fixed some virtual configuration problem with SCS sensors
- Several minor improvements and bug fixing

Hotel system:

- Management of a complete Hotel project (single room files generated with version 1.4.21 or previous of MyHome_Suite are not supported)
- Management of project with more than 100 rooms (require F458 or 003599)
- Added up to 10 custom contacts for each MH201 (require MH201 version 2.0 and Hotel Supervision version 1.2)
- Improvement of MH201 firmware updating
- Several minor improvements and bug fixing

Others:

- Correction of several translations
- Improvement in performance

New integrated products programming

Hotel IP Server: F458, 003599
Scenario programmer: MH202
Basic Gateway: F455, 003594 (only firmware update)
Classe 100 X12B: 344602 (only firmware update)
Classe 300 V13E/M: 344612, 344613, 344622 (only firmware update)

New products managed by virtual configuration

-

Fixed a problem with delay setting in fan coil modality. Thermostats: H4691, LN4691, 067459, 64170
Fixed a problem during the opening of an existing project
Fixed possible interaction problem with system firewall
Improvement of the catalogue search filter
Improvement of the USB communication. Touch screen: HC4690, HS4690, HD4690, 573962, 573963, 067285, H4890, LN4890, AM4890, 573958, 067292, 078479
Correction of some German translations
Added missed translations in different languages

New integrated products programming

-

Version: 1.3.32	Date: 10th March 2014
Corrected some translations New languages in "functions help" Minor bug fixing	
New integrated products programming	
IR Emitter: 3456, 088301	
New products managed by virtual configuration	
Key card switch: 572235	

Version: 1.3.24	Date: 11th November 2013
Minor bug fixing	
New integrated products programming	
IP scenario module: MH201	
New products managed by virtual configuration	
Hotel indicator DND-MUR bus: H4650, LN4650, 067590 Hotel reader DND-MUR bus: H4651, LN4651, 067591 DND-MUR command: H4653, LN4653,067593 Command 8 buttons: H4652, LN4652, 067592 Thermostat with display: H4691, LN4691, 067459 KeyCard reader RFID: H4648, 572736, 572236, 067566, 078480 KeyCard reader: H4649, 572735, 067565 Touch controls: 573912, 573913, 574091, 574591, HC/HS/HD4657M4, HC/HS4657M3, HD4657M3 Temperature control actuators: 003517, 003518, 003519, F430R3V10, F430R8, F430V10	

First release

Integrated products programming catalogue

Web server: F454 - 003598

Local display: HC4891, HS4891, HD4891, L4891, N4891, NT4891, 067271, 067272, 573716, 573917

Interface TCP-IP/2 wires: 346891

Touch screen 3,5": H4890, LN4890, LN4890A, AM4890, HW4890, 573958, 078479, 067292

Gateway Open-Bacnet: F450, 003597

Multimedia touch screen 10": HC4690, HS4690, HD4690, 573962, 573963, 067285

Web server: F453

Web server AV: F453AV, 573992

Virtual configuration catalogue

002600, 002601, 002602, 002604, 002611, 002612, 002621, 002622, 002631, 002645, 003551, 003552, 003553, 003554, 003555, 003557, 003558, 003559, 003562, 003565, 003577, 003579, 003580, 003597, 003598, 003652, 003653, 003656, 003665, 003841, 003842, 003843, 003844, 003845, 048820, 048821, 048822, 048823, 048824, 048825, 048826, 048828, 048829, 048830, 048831, 048832, 048833, 048840, 048841, 048842, 048843, 048844, 048845, 048847, 049238, 067206, 067207, 067216, 067217, 067218, 067225, 067226, 067241, 067242, 067243, 067244, 067245, 067249, 067273, 067274, 067275, 067281, 067282, 067293, 067294, 067295, 067455, 067456, 067457, 067458, 067552, 067553, 067554, 067556, 067557, 067558, 078462, 078463, 078465, 078466, 078467, 078469, 078471, 078472, 078473, 078475, 078478, 078485, 078486, 079171, 079172, 079173, 079175, 079178, 079262, 079263, 079265, 079266, 079267, 79269, 345829, 3475, 3476, 3477, 3522, 571848, 571849, 573900, 573901, 573902, 573903, 573904, 573905, 573906, 573907, 573916, 573917, 573918, 573919, 573920, 573921, 573922, 573923, 573924, 573925, 573961, 573974, 573975, 573985, 573987, 573991, 573992, 573996, 574046, 574048, 574089, 574096, 574098, 574503, 574504, 574589, 683090, 687376, 687377, 687378, 687390, 687890, AM5658, AM5659, AM5831/2, AM5831M2, AM5832/2, AM5832/3, AM5834, AM5851/1, AM5851/2, AM5851M2, AM5860M2, AM5861M2, AM5872, AM5875, BMDI1001, BMDI1002, BMDI3001, BMDI3002, BMDI3101, BMDI3301, BMNE4000, BMNE500, BMSE1001, BMSE2001, BMSE2002, BMSE2003, BMSE2004, BMSE2005, BMSE2006, BMSE2007, BMSE3001, BMSE3002, BMSE3003, BMSE3005, BMSW1001, BMSW1002, BMSW1003, BMSW1005, BMSW3001, BMSW3002, BMSW3003, F401, F411/1, F411/1FL, F411/1N, F411/1NC, F411/2, F411/2NC, F411/4, F413, F413N, F414, F414/127, F415, F415/127, F416U1, F417U2, F418, F420, F422, F425, F428, F429, F430/2, F430/4, F430FP, F450, F520, F521, F522, F523, F80/SG, F80/SGB, F80/SGP, H4651/2, H4651M2, H4652/2, H4652/3, H4655, H4660M2, H4661M2, H4671/1, H4671/2, H4671M2, H4674, H4678, HC/HS/HD4563, HC/HS/HD4575, HC/HS/HD4575SB, HC/HS/HD4577, HC/HS/HD4658, HC/HS/HD4659, HC/HS/HD4672N, HC/HS/HD4673, HC/HS/HD4680, HC/HS/HD4685, HC/HS/HD4692, HC/HS/HD4692FAN, HC/HS/HD4693, HC/HS4576, HC/HS4653/2, HC/HS4653/3, HC/HS4695, HD4576, HD4653M2, HD4653M3, HD4695, HS/HD/HC4654, L/N/NT4563, L/N/NT4575, L/N/NT4575N, L/N/NT4575SB, L/N/NT4576, L/N/NT4577, L/N/NT4654N, L/N/NT4658N, L/N/NT4659N, L/N/NT4672N, L/N/NT4673, L/N/NT4674, L/N/NT4675, L/N/NT4680, L/N/NT4685, L/N/NT4688, L/N/NT4692, L/N/NT4692FAN, L/N/NT4693, L/N/NT4695, L4651/2, L4651M2, L4652/2, L4652/3, L4655, L4671/1, L4671/2, L4678, LN4660M2, LN4661M2, LN4671M2, N4681