

MyHOME_Suite

Version history

Version: 3.5.5	Date: 6th May 2020
MyHomeServer1 and F459: fixed possible failure in firmware update	
New products managed by virtual configuration	
K8002L, K8002S, KW/KG/KM8010, KW/KG/KM8011 (only default icons), KW/KG/KM8013 (only onboard commands)	

Version: 3.5.3	Date: 31th January 2020
New integrated products programming	
MyHomeServer1: only firmware update Driver Manager F459: only firmware update	

Version: 3.4.25	Date: 4th October 2019
F454, F453AV, F453: field "ID Gateway", in MyHome portal chapter, now accept up to 7 characters	

Version: 3.4.18	Date: 21th June 2019
MyHome Screen 10" Capacitive; fixed a bug that occur during configuration of IrSplit in basic mode	
New integrated products programming	
Classe 100 X16E: 344682 (only firmware update)	

Version: 3.4.15	Date: 25th January 2019
<p>Fixed possible crash during creation of “new home”</p> <p>Restored link to manual and guide</p>	
New products managed by virtual configuration	
Basic probe with wired sensor: 3454	

Version: 3.4.7	Date: 18th October 2018
Minor bug fix	

Version: 3.4.4	Date: 27th June 2018
<p>F422: added full configuration capabilities</p> <p>MH202: added ability to duplicate a scenario</p>	
New products managed by virtual configuration	
K4652M2, K4652M3, K4672M2L, K4672M2S, KW4691, KG4691, KM4691, K4659	

Version: 3.3.73	Date: 8th May 2017
New icons for Classe300 BT-344612, 344613, 344622 (the firmware must be 2.00.06 or higher)	

Version: 3.3.70	Date: 26th October 2016
<p>Fixed a problem with actuator test function</p> <p>Fixed sporadic crashes</p> <p>Minor bug fix</p>	

Version: 3.3.65	Date: 05th August 2016
<p>Fixed sporadic problems opening old projects:</p> <ul style="list-style-type: none"> • MyHOME_Screen 10 C capacitive MH4892C, MH4893C, 067219, 067228 • Web Server F454 	

Version: 3.3.60	Date: 22th July 2016
<p>MyHOME_Screen 10 C capacitive MH4892C, MH4893C, 067219, 067228: bug fix</p> <p>Several optimizations and minor bug fixing</p>	
New integrated products programming	
<p>Classe 300 X13E: 344642, 344643 (only firmware update)</p>	

Version: 3.2.78	Date: 9th March 2016
<p>MyHome System:</p> <ul style="list-style-type: none"> - Thermostats H4691, LN4691 and 067459 produced after week 16W06: management of the new functions - MyHOME_Screen 10 C capacitive MH4892C, MH4893C, 067219, 067228: bug fix - Web Server F454: fixed sporadic conversion problem between version 1 and 2 <p>Hotel system:</p> <ul style="list-style-type: none"> - MH201 and 003593: management of version 3 - MH201 and 003593: fixed sporadic error during upload - <p>Access control:</p> <ul style="list-style-type: none"> - Central unit 348040: management of version 2.3 - Module GPRS 348330: management of version 1.1 <p>Several optimizations and minor bug fixing Tested with Windows 10</p>	
New integrated products programming	
-	
New products managed by virtual configuration	
-	

Version: 3.1.104	Date: 19th January 2016
-	
New integrated products programming	
-	
New products managed by virtual configuration	
2 relays+N actuator control: LN4672M2, H4672M2, AM5852M2, 067561, 064195, 064196, 064393	

Version: 3.1.94	Date: 26th October 2015
<p>MyHome System:</p> <ul style="list-style-type: none"> - Fixed errors in sensors configuration and related parameters <p>Hotel system:</p> <ul style="list-style-type: none"> - MH201 and 003593 configuration updating: possibility to set fancoil speed in scenario action <p>Optimizations and minor bug fixing</p>	
New integrated products programming	
<p>MyHOME_Screen 3.5 Version 4: LN4890, LN4890A, HW4890, H4890, AM4890, 573958, 078479, 067292 Webserver A/V bus Version 2: F454, 003598 Scenario Manager : MH200N, 003565 (only via Ethernet)</p>	
New products managed by virtual configuration	
<p>Dimmer energy saving lamps bus: F418U2, 003651 1 relay actuator 2 modules DIN bus: 003847 2 relay actuator 2 modules DIN bus: 003848 Dimmer 6 channels: 002627 8 channels DALI/SCS interface: BMDI1100, 002633 Wall mounted sensor long range: 048834</p>	

Version: 3.0.125	Date: 10th July 2015
Bug fixing: <ul style="list-style-type: none"> - possible coexistence problem with TiSferaDesign software - problems of user permissions in some PCs - problem converting some configuration files of MyHomeScreen 10" - function "copy room" in Hotel system 	
New integrated products programming	
-	
New products managed by virtual configuration	
-	

Version: 3.0.118	Date: 22th June 2015
Hotel system: creation of Hotel file able to manage Multi PC function (up to 10 Hotel Supervision Software in the same hotel) Optimizations and minor bug fixing	
New integrated products programming	
MyHOME_Screen 10 resistive: MH4892, MH4893, 067267, 067268 MyHOME_Screen 10 C capacitive (ready for coming launch): MH4892C, MH4893C, 067219, 067228	
New products managed by virtual configuration	
-	

Version: 2.0.111	Date: 20th March 2015
Optimizations and minor bug fixing	
New integrated products programming	
-	
New products managed by virtual configuration	
-	

Version: 2.0.104	Date: 6th February 2015
Fixed possible problem opening some configurations file made with version 1.x	
New integrated products programming	
-	
New products managed by virtual configuration	
-	

Version: 2.0.99	Date: 14th January 2015
<p>Graphics interface:</p> <ul style="list-style-type: none"> - Main page with definition of type of project (MyHome or Hotel) - A single view for virtual and product programming <p>MyHome system:</p> <ul style="list-style-type: none"> - Fixed some virtual configuration problem with SCS sensors - Several minor improvements and bug fixing <p>Hotel system:</p> <ul style="list-style-type: none"> - Management of a complete Hotel project (single room files generated with version 1.4.21 or previous of MyHome_Suite are not supported) - Management of project with more than 100 rooms (require F458 or 003599) - Added up to 10 custom contacts for each MH201 (require MH201 version 2.0 and Hotel Supervision version 1.2) - Improvement of MH201 firmware updating - Several minor improvements and bug fixing <p>Others:</p> <ul style="list-style-type: none"> - Correction of several translations - Improvement in performance 	
New integrated products programming	
<p>Hotel IP Server: F458, 003599 Scenario programmer: MH202 Basic Gateway: F455, 003594 (only firmware update) Classe 100 X12B: 344602 (only firmware update) Classe 300 V13E/M: 344612, 344613, 344622 (only firmware update)</p>	

New products managed by virtual configuration	
-	
Version: 1.4.21	Date: 30th July 2014
<p>Fixed a problem with delay setting in fan coil modality. Thermostats: H4691, LN4691, 067459, 64170</p> <p>Fixed a problem during the opening of an existing project</p> <p>Fixed possible interaction problem with system firewall</p> <p>Improvement of the catalogue search filter</p> <p>Improvement of the USB communication. Touch screen: HC4690, HS4690, HD4690, 573962, 573963, 067285, H4890, LN4890, AM4890, 573958, 067292, 078479</p> <p>Correction of some German translations</p> <p>Added missed translations in different languages</p>	
New integrated products programming	
-	

Version: 1.3.32	Date: 10th March 2014
<p>Corrected some translations</p> <p>New languages in "functions help"</p> <p>Minor bug fixing</p>	
New integrated products programming	
<p>IR Emitter: 3456, 088301</p>	
New products managed by virtual configuration	
<p>Key card switch: 572235</p>	

Version: 1.3.24	Date: 11th November 2013
<p>Minor bug fixing</p>	
New integrated products programming	
<p>IP scenario module: MH201</p>	
New products managed by virtual configuration	
<p>Hotel indicator DND-MUR bus: H4650, LN4650, 067590</p> <p>Hotel reader DND-MUR bus: H4651, LN4651, 067591</p> <p>DND-MUR command: H4653, LN4653, 067593</p> <p>Command 8 buttons: H4652, LN4652, 067592</p> <p>Thermostat with display: H4691, LN4691, 067459</p> <p>KeyCard reader RFID: H4648, 572736, 572236, 067566, 078480</p> <p>KeyCard reader: H4649, 572735, 067565</p> <p>Touch controls: 573912, 573913, 574091, 574591, HC/HS/HD4657M4, HC/HS4657M3, HD4657M3</p> <p>Temperature control actuators: 003517, 003518, 003519, F430R3V10, F430R8, F430V10</p>	

First release

Integrated products programming catalogue

Web server: F454 - 003598
 Local display: HC4891, HS4891, HD4891, L4891, N4891, NT4891, 067271, 067272, 573716, 573917
 Interface TCP-IP/2 wires: 346891
 Touch screen 3,5": H4890, LN4890, LN4890A, AM4890, HW4890, 573958, 078479, 067292
 Gateway Open-Bacnet: F450, 003597
 Multimedia touch screen 10": HC4690, HS4690, HD4690, 573962, 573963, 067285
 Web server: F453
 Web server AV: F453AV, 573992

Virtual configuration catalogue

002600, 002601, 002602, 002604, 002611, 002612, 002621, 002622, 002631, 002645, 003551, 003552, 003553, 003554, 003555, 003557, 003558, 003559, 003562, 003565, 003577, 003579, 003580, 003597, 003598, 003652, 003653, 003656, 003665, 003841, 003842, 003843, 003844, 003845, 048820, 048821, 048822, 048823, 048824, 048825, 048826, 048828, 048829, 048830, 048831, 048832, 048833, 048840, 048841, 048842, 048843, 048844, 048845, 048847, 049238, 067206, 067207, 067216, 067217, 067218, 067225, 067226, 067241, 067242, 067243, 067244, 067245, 067249, 067273, 067274, 067275, 067281, 067282, 067293, 067294, 067295, 067455, 067456, 067457, 067458, 067552, 067553, 067554, 067556, 067557, 067558, 078462, 078463, 078465, 078466, 078467, 078469, 078471, 078472, 078473, 078475, 078478, 078485, 078486, 079171, 079172, 079173, 079175, 079178, 079262, 079263, 079265, 079266, 079267, 79269, 345829, 3475, 3476, 3477, 3522, 571848, 571849, 573900, 573901, 573902, 573903, 573904, 573905, 573906, 573907, 573916, 573917, 573918, 573919, 573920, 573921, 573922, 573923, 573924, 573925, 573961, 573974, 573975, 573985, 573987, 573991, 573992, 573996, 574046, 574048, 574089, 574096, 574098, 574503, 574504, 574589, 683090, 687376, 687377, 687378, 687390, 687890, AM5658, AM5659, AM5831/2, AM5831M2, AM5832/2, AM5832/3, AM5834, AM5851/1, AM5851/2, AM5851M2, AM5860M2, AM5861M2, AM5872, AM5875, BMDI1001, BMDI1002, BMDI3001, BMDI3002, BMDI3101, BMDI3301, BMNE4000, BMNE500, BMSE1001, BMSE2001, BMSE2002, BMSE2003, BMSE2004, BMSE2005, BMSE2006, BMSE2007, BMSE3001, BMSE3002, BMSE3003, BMSE3005, BMSW1001, BMSW1002, BMSW1003, BMSW1005, BMSW3001, BMSW3002, BMSW3003, F401, F411/1, F411/1FL, F411/1N, F411/1NC, F411/2, F411/2NC, F411/4, F413, F413N, F414, F414/127, F415, F415/127, F416U1, F417U2, F418, F420, F422, F425, F428, F429, F430/2, F430/4, F430FP, F450, F520, F521, F522, F523, F80/SG, F80/SGB, F80/SGP, H4651/2, H4651M2, H4652/2, H4652/3, H4655, H4660M2, H4661M2, H4671/1, H4671/2, H4671M2, H4674, H4678, HC/HS/HD4563, HC/HS/HD4575, HC/HS/HD4575SB, HC/HS/HD4577, HC/HS/HD4658, HC/HS/HD4659, HC/HS/HD4672N, HC/HS/HD4673, HC/HS/HD4680, HC/HS/HD4685, HC/HS/HD4692, HC/HS/HD4692FAN, HC/HS/HD4693, HC/HS4576, HC/HS4653/2, HC/HS4653/3, HC/HS4695, HD4576, HD4653M2, HD4653M3, HD4695, HS/HD/HC4654, L/N/NT4563, L/N/NT4575, L/N/NT4575N, L/N/NT4575SB, L/N/NT4576, L/N/NT4577, L/N/NT4654N, L/N/NT4658N, L/N/NT4659N, L/N/NT4672N, L/N/NT4673, L/N/NT4674, L/N/NT4675, L/N/NT4680, L/N/NT4685, L/N/NT4688, L/N/NT4692, L/N/NT4692FAN, L/N/NT4693, L/N/NT4695, L4651/2, L4651M2, L4652/2, L4652/3, L4655, L4671/1, L4671/2, L4678, LN4660M2, LN4661M2, LN4671M2, N4681