

IP Scenario Module

MH201 - 003593

Version history

Firmware Version: 3.5.10	Date: 16 th Sept 2022
<p>New feature:</p> <ul style="list-style-type: none">• Addition of reset to DHCP IP mode on a between 10 and 15 seconds push on the button.• Addition of a full reset of the flash files of the MH201 on a more than 20 seconds push on the button. <p>Performances improvements/Bug correction:</p> <ul style="list-style-type: none">• MH201 does not reset anymore its internal datetime after each write to the internal clock.• Addition of a watchdog to the http service if it appears to get blocked• Correction of a bug which made some unexpected data written in the file containing the badges info and the file containing the TCP/IP stats• Various performance improvements and minor bug corrections <p>To update firmware use MyHotelSuite version 5.0.x or upper.</p> <p>This FW version is only compatible with Hotel Supervision Software version from 2.5.3</p>	

Firmware Version: 3.3.6	Date: 1 st October 2019
<p>New feature:</p> <ul style="list-style-type: none">• Support of the Keycard Reader devices:<ul style="list-style-type: none">○ Recording of the Badge user type in case of power/LAN failure○ Scenarii management○ Update of the Badge User type on Hotel Supervision Software <p>Performances improvements/Bug correction:</p> <ul style="list-style-type: none">• Correction of a bug which made the MH201 reset unexpectedly• Now when a delay or a temporizing is configured in a scenario, its duration is not doubled anymore• Various performances improvements and minor bug fixing. <p>To update firmware use MyHotelSuite version 5.x.x or upper.</p>	

Firmware Version: 3.2.6	Date: 8th June 2018
<p>New feature:</p> <ul style="list-style-type: none"> • Support of the new Room Generic Service feature: <ul style="list-style-type: none"> ○ Recording of the RGS state in case of Power/LAN failure ○ Scenarii management ○ Update of the RGS state on Hotel Supervision Software <p>Performances improvements/Bug correction:</p> <ul style="list-style-type: none"> • Correction of a bug which set the “Master Badge” field to “Yes” in MyHotelSuite after receiving a MH201 configuration. • Correction of a bug which made the MH201 launch unexpected alarms. • Various performances improvements and minor bug fixing. <p>To update firmware use MyHotelSuite version 4.2.0 or upper.</p>	

Firmware Version: 3.0.1	Date: 11th March 2016
<p>Optimization and minor bug fixes</p> <p>To update firmware use MyHomeSuite version 3.2.78 or upper.</p>	

Firmware Version: 2.1.8	Date: 1th July 2015
<p>Improvements in:</p> <ul style="list-style-type: none"> - memory module management - network connection - scenario management 	

Firmware Version: 2.0.34	Date: 28th January 2015
<p>Added up to 10 custom contacts (require Hotel Supervision version 1.2)</p> <p>Minor bug fixes</p>	

Firmware Version: 1.1.38	Date: 11th June 2014
<p>Minor bug fixes</p>	

Firmware Version: 1.0.53	Date: 22th January 2014
<p>Several improvements in scenarios management</p> <p>Minor bug fixes</p>	