



## **Web Server**

F454 - 003598

# **Version history**

Firmware Version: 2.0.51 Date: 8th May 2017

Fixed a problem in web pages during visualization of thermoregulation probe status

Firmware Version: 2.0.50 Date: 16th May 2016

Fixed occasional problem during visualization of real-time images Optimization and minor bug fixing

Firmware Version: 2.0.48 Date: 26th January 2016

Optimization and minor bug fixing

## Firmware Version: 2.0.46 Date: 28th October 2015

#### New features:

- brand new web pages and profile management
- compatibility with MyHome\_Web APP
- burglar alarm activation/deactivation

#### Improvements:

- Updated SSL certificate
- HMAC authentication can be enabled
- Improved MyHome Portal communication
- Optimization and minor bug fixing

Firmware Version: 1.0.51 Date: 18th November 2014

Several improvements with MyHome portal

# Firmware Version: 1.0.45 Date: 12th February 2013

Corrected some translations (web pages) Improvement of video streaming performance Minor bug fixes

Firmware Version: 1.0.37 Date: 17th June 2013

Improvement of performance during virtual configuration phases Minor optimizations

Firmware Version: 1.0.32 Date: 30th July 2012

Improvement of cyber security
Minor bug fixes (burglar alarm system)

Firmware Version: 1.0.26 Date: 29th February 2012

First release